

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 10065754	
4. Organization Name and Address: Ametek MRO Florida Inc. dba Avtech Avionics & Instruments 7370 NW 35th Street Miami, FL. 33122 US		Repair Station No.: 1VTR273B		5. Work Order, Contract or Invoice Number: Work Order No.: ARA104751 Customer RO.: A102311	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	INERTIAL REFERENCE U	HG1050AD11	1.00	5569	REPAIRED

12. REMARKS

Repaired in accordance with CMM: 34-27-05 Rev: 11 Dated: 05-Jun-2013. Full details of work performed can be found in teardown/inspection report ARA104751

SB's incorporated: None
 FAA AD's incorporated: None
 EASA AD's incorporated: None

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number EASA.145.6180.

13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12		14a <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12
13b. Authorized Signature:		14b. Authorized Signature: <i>Jantton</i>
13c. Approval/Authorization No:		14c. Approval/Certificate No: 1VTR273B
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): Alvin Jantton
13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 12/Dec/2018

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Ametek MRO Florida Inc.

dba Avtech Avionics & Instruments
7370 NW 35th Street
Miami, FL. 33122
US

Tear Down/Inspection

Work Order #: ARA104751

Date Completed: 12/Dec/2018

PO Number: A102311

Page: 1 of 1

To:
ATTN: TERRY J. CAIN
JET MIDWEST, INC.
9200 N.W. 112 STREET BLDG #2
KANSAS CITY, MO 64153
UNITED STATES

Ship To:
JET MIDWEST, INC.
9200 N.W. 112 STREET BLDG #2
KANSAS CITY, MO 64153 UNITED STATES

Part Number: HG1050AD11
Description: INERTIAL REFERENCE U
Service Performed: REPAIRED

Serial Number: 5569
Manufacturer: HONEYWELL
Repair Station: 1VTR273B

Data Used: Manual Number: 34-27-05 Rev: 11 Date: 05-Jun-2013

Teardown/Inspection Data

1. Reason for Removal: TEST AND RECERTIFY FOR 8130 Inst: Repair as necessary

2. Initial Inspection Findings
Appearance: Normal Corrosion: No Corrosion Noted.
Loose or Missing Parts: No Loose or Missing Parts. Physical Damage: No damage found.

3. Teardown
Disassembly: Only as Required for Repair Cleaning: Performed cleaning as required
Painting: None Performed. Assembly: As Required

4. Test
Operation: TESTED I/AW Mfg Specs. Was Complaint Verified: Yes
Modifications: NONE Other problems found: Repaired

5. Final
Warranty Accepted: N/A Final Test and Inspection: Final Inspection Normal
A.D. S.B. NO A.D. / S.B. REQUIRED

6. Work Performed: Rebiased and tested in accordance with manufacturer's specifications.

MAINTENANCE RELEASE

This certifies the item identified above was serviced in accordance with current F.A.A. airworthines regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work Order No:- ARA104751

Inspector's Name : Alvin Janton

Technician: Lenroy Samuels

Signature: *Janton*

Date: 12/Dec/2018