


<b>1. Approving Competent Authority / Country</b> <b>Civil Aviation Administration of the Republic of Lithuania</b>		<b>2. AUTHORISED RELEASE CERTIFICATE</b> <b>EASA FORM 1</b>			<b>3. Form Tracking Number</b> <b>WS20-12508</b>
<b>4. Organisation Name and Address:</b> <b>UAB "BAL TIC maintenance"</b> <b>Address: Meistrų g. 8, Vilnius LT-02189, Lithuania</b>					<b>5. Work order/Contract/ Invoice</b> <b>RO20021302</b>
<b>6. Item</b>	<b>7. Description</b>	<b>8. Part No</b>	<b>9. Qty.</b>	<b>10. Serial No</b>	<b>11. Status/Work</b>
<b>1</b>	Nose wheel assembly	2607825-2	1	Outboard wheel subassy <b>B8121</b> Inboard wheel subassy <b>B8121</b>	<input checked="" type="checkbox"/> Overhauled <input type="checkbox"/> Inspected/Tested <input type="checkbox"/> Modified <input type="checkbox"/> Repaired
<b>12. Remarks</b> Overhaul was made in accordance with CMM 12-579 (32-40-10) rev. 11 and SPM 12-688 (32-49-01) rev. 4, temporary rev. 32-7/-8. Installed / replaced parts and additional repairs / works are indicated in BM Workshop Report No. 12508. NDT works were carried out in accordance with SPM 12-688 (32-49-01) rev. 4, temporary rev. 32-7/-8.  The number of accumulated self-locking nut P/N 2615046 / NAS1804-7 installations on the tie bolts is 1 CSN=Unk CSO=0					
<b>13a.</b> Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in condition for safe operation <input type="checkbox"/> non-approved design data specified in block 13		<b>14a.</b> <input checked="" type="checkbox"/> Part-145 A.50 Release to Service <input type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
<b>13b.</b> Authorised Signature		<b>13c.</b> Approval/Authorisation Number		<b>14c.</b> Certificate/Approval Ref. No <b>LT.145.009</b>	
<b>13d.</b> Name		<b>13e.</b> Date (dd mmmm yyyy)		<b>14e.</b> Date (dd mmmm yyyy) <b>12 Mar 2020</b>	
<b>14b.</b> Authorised Signature 					
<b>14d.</b> Name <b>Artūras Zadojenko</b>					
<b>USER/INSTALLER RESPONSIBILITIES</b> This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

Workshop Job Card No. <b>WS -12508</b>	Customer: <b>BALTIC maintenance</b>	Component P/N: <b>2607825-2</b>	Description: <b>Nose wheel assembly</b>
Job Card Issue Date: <b>13 Feb 2020</b>	Customer's Repair Order No.: <b>RO20021302</b>	Outboard wheel subassy <b>B8121</b>	Ordered Works: <b>Overhaul</b>
Works accomplished on <b>12 Mar 2020</b>		Inboard wheel subassy <b>B8121</b>	

Labour Price for Ordered Works	Sub-Total, EUR	Remarks
Price for Consumables	<b>0.00</b>	
Additional or Non-Routine Works	<b>0.00</b>	
	<b>0.00</b>	Cup replacement
	<b>0.00</b>	


**Parts Installed or Replaced by:**

Item No	Part No.	Description	Serial, batch, lot No. (if applicable)	Invoice No.	q-ty	Unit Price, EUR	Sub-Total, EUR	Reason for Replacement
1	L507945	Bearing Cone	HY	1162988	1	0.00	0.00	Corroded
2	L507949	Bearing Cone	JF	1162988	1	0.00	0.00	Corroded
3	L507910	Bearing Cup	JH	1161504	1	0.00	0.00	Corroded
4	L507910	Bearing Cup	JH	1161504	1	0.00	0.00	Corroded
5	2601284	Packing	18-309	23912171	1	0.00	0.00	Bumped
6	448	Packing		9309682463	1	0.00	0.00	Overhaul
7	2609691	Plate		19FTRP-000491	1	0.00	0.00	Overhaul
8	AS3582-012	Packing		9308552137	1	0.00	0.00	Overhaul
9	637	Valve cap	18-242	9308408288	1	0.00	0.00	Missing
10	402AH	Valve core	18-023	9309062273	1	0.00	0.00	Missing
11	NAS1351-3H14P	Screw	28262d	HNFEJ	1	0.00	0.00	Damage head
12	NAS679A3	Nut		9308552137	3	0.00	0.00	No self locking
13	NAS1804-7	Nut	87391	FTQ1082906	4	0.00	0.00	No history
14	NAS1804-7	Nut	99800	FTQ1092099	10	0.00	0.00	No history

Note: Copies of certificates for the installed and replaced parts will be provided on request.

Total for maintenance: **0.00** EUR

**Artūras Zadojenko**



**12 Mar 2020**