



FAA REPAIR STATION 68IR700B
 EASA REFERENCE 145.6295
 2617 Executive Point Dr
 Monroe, NC 28110
 Ph: 704.821.4266 Fax:
 Email: quotes@iconaerospace.com

WORK ORDER

W164443

Date Released: 17/Sep/2021

TEARDOWN REPORT

GOAL AVIATION	Cust RO#: 650210037	Manuals
Rybí 116, 742 65	P/N: 45-0083-7	Loc ATA Revision
Contact: QUOTES	S/N: 6069	HW-002 33-40-15 12 15/Nov/2019
Contact Ph: 420 601 313 587	Desc: LIGHT, RETRACTABLE LANDING	
Contact Fax:	Mfgr: HONEYWELL.	
Work Requested UNIT RECEIVED FOR OVERHAUL AS PER O.E.M SPECS		

FINDINGS

RECEIVING INSPECTION:
 VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND. UNIT RECEIVED OPEN.

PRELIMINARY INSPECTION:
 FAILED

HIDDEN DAMAGE:
 NONE

CONTINUED INSPECTION:
 TESTED. UNIT FAILED FUNCTIONAL TEST. FOUND UNIT DIRTY. UNIT HAS A BAD LAMP AND ACTUATOR.
 DISASSEMBLY IS REQUIRED.

CORRECTIVE ACTION:UNIT CONDITION OVERHAULED
 REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLED UNIT. ALL WORK PERFORMED AS PER O.E.M SPEC'S.

SB'S, AD'S AND RMK'S:
 NONE

CERTIFICATION

SERVICE PERFORMED: OVERHAULED

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION	COND
1	46-0627-1	ACTUATOR SWITCH	FN
1	4635	LAMP	FN

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: Agustin Garcia DATE: 17/Sep/2021

1. Approving Civil Aviation Authority/Country: FAA/United States

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: 650210037

4. Organization Name and Address: Icon Aerospace, LLC
2617 Executive Point Dr
Monroe, NC 28110

FAA Repair Station : 681R700B
EASA Reference : 145.6295
Ph: 704.821.4266 Fax:

5. Work Order/Contract/Invoice Number: **W164443**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	LIGHT, RETRACTABLE LANDING	45-0083-7	1	6069	OVERHAULED

12. Remarks: OVERHAULED in accordance with HONEYWELL. CMM 33-40-15 Rev.:12 Date:15/Nov/2019

FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W164443

COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADs):
N/A

COMPLIANCE WITH SERVICE BULLETINS (SBS/EOS):
N/A

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12.


13b. Authorized Signature:

13c. Approval/Authorization No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12.

14b. Authorized Signature: 

14c. Approval/Authorization No.: 681R700B

14d. Name (Typed or Printed): Agustin Garcia

14e. Date (dd/mm/yyyy): 17/Sep/2021

14b. Authorized Signature:

14c. Approval/Authorization No.:

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.